



Схемы соединений



Обозначение	L, мм	d, мм	Масса, г, не более
ТСМ.ГПКШ.039	80	6	100
- 01	80	8	140
- 02	100	8	150
- 03	100	6	110
- 04	120	8	160
- 05	160	8	180
- 06	200	8	200
- 07	250	8	250
- 08	320	8	260
- 09	500	8	350